

BMP	BMP ID Project Name	BMP Address	Date and Time Assessed	Lat/Long	BMP Type	BMP Description	Current Site Issues	Site Description	Feasibility Issues	Landowner where BMP is Located	New or Existing BMP	Soil	Primary LULC	Impervious Contributors
Nalik	Project Name	Address	Assesseu	Lat/Long	Bivir Type	BIVIF DESCRIPTION	Current site issues	Site Description	reasibility issues	Locateu	DIVIF	Стоир	Filliary LOLC	Contributors
		Packard Rd		44.509431, -		Large infiltration basin in Town-owned		Low-lying vegetation, open and						
1	214 Town Parcel Infiltration Basin	and VT-15	11/1/2016 13:25	1	Infiltration Basin	•	Area subject to annual, seasonal flooding	, , , , , , , , , , , , , , , , , , , ,	Mixed soils	Town	New	A/D	Other	Public, Private
	South Main Street Undergroun	d	, ,			Underground chambers in						1		, , , , , ,
	Storage and Infiltration			44.508808, -	Underground Storage	undeveloped parcel to mitigate	This is a chronic problem area subject to	Parcel of undeveloped land adjacent	Currently under an existing				Road,	
2	56 Chambers	So Main St	11/1/2016 13:00	72.967443	and Infiltration Chambers	neighborhood-wide flooding	annual, seasonal flooding	to the entrance of South Main Street	stormwater permit	Private	New	Α	Residential	Public, Private
						Underground chambers beneath lower	Streambank erosion and poor pavement							
						parking lot to collect and infiltrate a	quality due to stormwater ponding;		Parking lot closure during					
	MMU Underground Storage an	d 211 Browns		44.485306, -	Underground storage	large percentage of the school's	stormwater currently discharges directly		construction; currently under an					
3	235 Infiltration Chambers	Trace Rd	10/27/2016 11:50	72.964034	and infiltration chambers	stormwater	to a Lee River tributary	Lower parking lot	existing stormwater permit	Town/School	New	Α	Educational	Public
						Infiltration basin in the grassy island								
		22 Jericho				across from the Town green; will	Large drainage area with little existing							
	Jericho Center Circle Infiltration	Center		44.469409, -		accept drainage from Bolger Hill Rd,	stormwater infrastructure; drains to	Grassy island across from the Town	Space restrictions, moderate					
4	206 Basin	Circle	10/18/2016 10:36	72.973229	Infiltration Basin	the Town green, and Browns Trace	wetland	green	slope, and tree roots	Town	New	А	Road	Public, Private
	Jericho East Park Underground	So Main St				Underground chambers to accept			Moderate slope, utility issues					
	Storage and Infiltration	and Kriste		44.507928, -	Underground storage		Drainage area contributes to annual,		possible, and under an existing				Road,	
5	125 Chambers	Ln	11/1/2016 13:00	72.965967	and infiltration chambers	subdivision	seasonal flooding along lower South Main		stormwater permit	Private	New	Α	Residential	Public, Private
								Area located at the intersection of						
		Dickensen					Large amount of impervious surface	· ·	Utility issues (observed fiber					
		St and River		44.520163, -			within a large drainage area; drains to the		-	Private;				Public, Private,
6	35 Dickenson Street Gravel Wetlan	nd Rd	11/1/2016 12:22	72.945500	Gravel wetland	flow to the Browns River	Browns River	middle school	wetland in space by the school	Town/School	New	В	Commercial	Commercial



		Proximity to	Drainage	Impervious Area Managed	Impervious Area Managed		BMP Footprint	BMP Practice	Project	Project Cost	Cost Rounded to Nearest	Cost/Impervious Acre		Ease of O/M	Volume Managed	Volume Managed	Volume Managed (ac-	Volume	CPv Controlled	d CPv Controlled	Primary or Secondary	Primary or Secondary
Project Name	Stormwater Permit(s)	•	Area (acres)	_	•	% Imp.	(acres)	Depth (ft)	Cost	Score	\$1,000	Managed	Ease of O/M	-	(1/2WQ, WQ, CPv)	Score	ft)	Score	(yes, no)	(score)	ВМР	BMP (score)
						4-04																
Town Parcel Infiltration Basin		199.85	77	11.471	6	15%	0.11	5	\$42,734	3	\$43,000	\$3,725	Infiltration Basin	1	CPv	3	2.056		5 Yes	1 1	Primary	İ
South Main Street Underground		155.05	, , , , ,	11.471			0.11	3	Ş12,731		\$43,000	<i>ϕ3,123</i>	Dusin			3	2.030		103		Timur y	
_	Current permit 3328-9010 for					17%									CPv							l
Chambers	Jericho East Subdivision	128.18	47	8.00	5		0.13	5.5	\$226,403	2	\$226,000	\$28,297	Chambers	3		3	1.533	į	Yes	1	Primary	
	Current permit 3009-9010.R																					
MMU Underground Storage and	·					87%																i .
	High School	17.33	9	8.16	5		0.17	5.5	\$226,403	1	\$226,000	\$27,745	Chambers	3	CPv	3	1.213	ţ	Yes	1	Primary	<u> </u>
Jericho Center Circle Infiltration						21%							Infiltration									ı
Basin		271.43	3 12	2.613	3		0.06	4	\$48,158	3	\$48,000	\$18,430		1	CPv	3	0.643		Yes	1	Primary	1
Jericho East Park Underground									, ,			, ,									,	1
	Current permit 3328-9010 for					14%																ı
Chambers	Jericho East Subdivision	197.61	29	4.112	4		0.13	5.5	\$223,622	2	\$224,000	\$54,383	Chambers	3	CPv	3	1.248	į	Yes	1	Primary	
						29%							Gravel									
Dickenson Street Gravel Wetland		327.86	35	10.198	6		0.14	6	\$477,865	1	\$478,000	\$46,859	Wetland	0	CPv	3	0.914	į	Yes	1	Primary	



Project Name	Permitting Restrictions	Permitting Restrictions (score)	Land Owner Description	Land Availability where BMP is Located	Land Availability where BMP is Located (score)	Flood	Flood Mitigation (score)	TSS Removal (% Yield Reduction)	Reduction in TSS (lbs)	Reduction in TSS (score)	\$/Ib TSS Removed	lbs TSS Removed/acr e	TP Removal (% Yield Reduction)		Reduction in TP (score)	\$/lb TP Removed	lbs TP Removed/acr e	Other Project Benefits/ Constraints	Other Project Benefits/ Constraints (score)	Total Score
						Infrastructure		67%					66%							
Town Parcel Infiltration Basin	No Permits	2	Town	Town owned	4	Damage	2	0770	102,478	4	\$0.42	1330	0070	147	4	\$291	2	N/A	1	37
South Main Street	Minimal Issues/Concerns; current										7					7-2-	_			
Underground Storage and	permit 3328-9010 (Jericho East					Neighborhood-		75%					75%							
Infiltration Chambers	Subdivision)	2	Private	Unknown	C	Wide Flooding	3		74,099	3	\$2	1564		108	3	\$1,238	2	N/A		32
MMU Underground Storage	Minimal Issues/Concerns; current permit 3009-9010.R (Mount			Not Town owned/				98%					98%					Educational Benefit, Infrastructure		
and Infiltration Chambers	Mansfield Union High School)	2	School	Participatory Owner	2	Nuisance Issue	1		5,384	1	\$42	573		9	1	\$24,441	1	Improvement	2	2 29
Jericho Center Circle Infiltration Basin	No Permits	2	2 Town	Town owned	4	Nuisance Issue	1	76%	22,956	2	2	2 1866	76%	33	2	\$1,456		Infrastructure Improvement; Uncertainty		29
Jericho East Park Underground	Minimal Issues/Concerns; current																			
Storage and Infiltration	permit 3328-9010 (Jericho East							78%					78%					Utility issues	1	
Chambers	Subdivision)	2	2 Private	Unknown	C	None	0		59,868	3	\$4	2078		87	3	\$2,564	3	(possible)	-1	1 27
Dickenson Street Gravel Wetland	Minimal Issues/Concerns; nearby permits include: 7424-9020 (Jericho Marke), and 7593-INDS (CCTA Park and Ride Jericho)		2 Private	Unknown		None	0	48%	33,930	2	\$14	ı 969	46%	103	3	\$4,639	3	Utility issues	-1	1 24